



Qualitäts-Maßstäbe

Special feature angle overview



45°



Angle overview – Measure fast and exactly

As per standard, the angle overview is located on the inside of the first section. It allows fast and exact readings in 15° steps. More features and designs, special measuring sticks and graduations on request.